FFC (TRADE TEST) 2007

- 1) Corrosion resistance property of metal?
 - i. Chromium
 - ii. Nickel
 - iii. Carbon
 - iv. All above
- 2) (18 4 1) This is H.S.S Percentage?
 - i. Chromium, Nickle, Carbon
 - ii. Chromium, Vanadium, Nickle
 - iii. Nickel, Tungiston, Vanadium
 - iv. Cr, V, W
- 3) Which part is not used in Diesel engine?
 - i. Carbourator
 - ii. Spark plug
 - iii. Piston
 - iv. Piston rod
- 4) 100m³ of air contain?
 - i. 87 % m³ of Oxygen.
 - ii. 78 % m³ of Oxygen
 - iii. 29 % m³ of Oxygen
 - iv. 21 % m³ of Oxygen.
- 5) Composition of Brass?
 - i. Copper + tine.
 - ii. Copper + Zink
 - iii. Nickel + Copper
 - iv. Brass + Copper
- 6) The process in I.C engine?
 - i. Adiabatic
 - ii. Isothermal
 - iii. Isometric
 - iv. Non above
- 7) Slip of belt is occurred?
 - i. Load
 - ii. Tension b/w belts.
 - iii. Creep
 - iv. Tension of load.

- 8) If increase the acetylene gas in the flame is called?
 - i. Carborizing flame.
 - ii. Neutral flame.
 - iii. Oxidizing flame.
 - iv. Non above
- 9) Casting is used?
 - i. For change of volume.
 - ii. For change shape.
 - iii. For change temperature
 - iv. Non above
- 10) If the percentage of Carbon in iron is increase till 2.11 % there is called?
 - i. Pig iron.
 - ii. Cast iron.
 - iii. Wrought iron.
 - iv. Non above
- 11) Which one of the following devices generates current through chemical action?
 - i. Generator
 - ii. Dynamo
 - iii. Dryeell
 - iv. Motor
- 12) Repeated time which load is applied on a body in elastic limit causes?
 - i. Endurane
 - ii. Elasticity
 - iii. Plasticity
 - iv. Fatigue
- 13) Resistance of metal for permanent indentation is called?
 - i. Hardness
 - ii. Toughness
 - iii. Elasticity
 - iv. Plasticity
- 14) In Electric arc welding is
 - i. Constant voltage.
 - ii. Constant current.
 - iii. High voltage.
 - iv. High current.
- 15) Which process is performed when tool is perpendicular?
 - i. Turning
 - ii. Milling
 - iii. Facing
 - iv. Non above

16) Which process is used when a hole is do much larger?

- i. Reaming
- ii. Turning
- iii. Boring
- iv. Broching

17) Density

- i. Increase with increase in temp.
- ii. Decrease with increase in temp.
- iii. Constant
- iv. Non above

18) Steam trape is used:

- i. For trape the steam.
- ii. To trape water.
- iii. To drain costenate water.
- iv. Non above

19) Heat transfer resources:-

- i. Conduction
- ii. Conduction, Convection
- iii. Conduction, Radiation
- iv. Conduction, Convection. Radiation

20) In throttling process constant thug is?

- i. Volume
- ii. Temperature
- iii. Pressure
- iv. Non above